

EXTERIOR WALLS: MASONRY, STUCCO, ETC.

WARNING Listing of a Contractor does not constitute a recommendation by the Presbytery or the Property Ministries Team. Churches considering hiring a Contractor from this list are advised first to speak to the listed "Contact for Information" Information is intended to be accurate at time of listing. Please let PMT know of changes or inaccuracies encountered.

NAME/ADDRESS/TELEPHONE	EMPLOYED BY/ CONTACT FOR INFORMATION	EMPLOYED FOR/DATE
Garfield Building Maintenance Co. 6638 W. 99th Pl., Chicago Ridge, 60415 708-424-2002, Dave Downey	Agape House, Chicago Vida Nueva Presbytery offices, Chicago Lake View Bob Hutchins, PMT, 773-348-6216	Tuckpointing, common/face brick restor. Parapet rebuilding, brick restoration 2001 et al.
Kelly Plastering Co. 10468 Sutton Dale, Frankfort, 60423 815-464-0606, Dave Kelly	Presbytery offices Bob Hutchins, PMT, 773-348-6216	Exterior stucco, drivit, 2003
Marion, Inc. 4340 W. Addison, Chicago, 60641 773-286-4100, Al Christoffer	Chicago Lake View Chicago Irving Park (former) Bob Hutchins, PMT, 773-348-6216	Rustic limestone restoration 1998 Parapet rebuilding, 2002
Reliable Building Systems, Inc. 2422 Dempster, Evanston, 60202 847-869-2002, Jim Owen	Presbytery offices Bob Hutchins, PMT, 773-348-6216	Monitor recaulking, 2003 (also do masonry repair, tuckpointing)